03500.017406 JUN 1 2 2006 JUN 1



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	Examiner: Hoang Ngo
Yasunari WATANABE, et al.)	
U.S. Patent No.: 6,999,690 B2	;	Group Art Unit: 2852
Issued: February 14, 2006	;)	Confirmation No.: 2715
Appl. No.: 10/617,024)	
Filed: July 11, 2003)	
For: IMAGE FORMING APPARATUS	:)	June 12, 2006

Commissioner for Patents Post Office Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Certificate
JUN 1 4 2006

of Correction

06/13/2006 FMETEKI1 00000022 6999690

01 FC:1811

100.00 OP

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our New York office at the address given below.

Respectfully submitted,

William M. Wannisky Attorney for Patentees

Registration No. 28,373

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 Facsimile: (212) 218-2200

WMW\tas

DC_MAIN 242785v1

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,999,690 B2

DATED

February 14, 2006

INVENTOR(S) :

Yasunari WATANABE, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4:

Line 42, "cylinder" should read --cylinder (conductive drum substrate) 1a.--; Line 44, "(Conductive Drum Substrate) 1a." should be deleted.

COLUMN 5:

Line 1, "an" should read --a--;

Line 2, "roller," should read --roller, and the surface layer 2d is a protection layer provided for preventing a leak from occurring even if a flaw such as a pinhole exists on the photosensitive drum 1. To be more specific, specifications of the charging roller--;

Line 10, "The" should read -- The--; and

Line 15, "Surface" should read -- Surface--.

COLUMN 7:

Line 15, "rum 1" should read --drum 1--;

Line 26, "copy)" should read --copy).--; and

Line 53, "work." should read --work. Further, this cleanerless system has a merit in terms of downsizing the image forming apparatus. According to this embodiment, the transfer residual toner on the surface of the photosensitive drum 1 after being the transferred, is conveyed to the developing portion "c" via the charging portion "a" and the exposing portion "b" as the photosensitive drum 1 subsequently rotates, and is cleaned (collected) simultaneously with developing by the developing device 4.--.

COLUMN 8:

Line 26, "charging" should read --improper charging--; and Line 27, "improper" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. 6,999,690 B2

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82)

WMW\tas

Stable Here Ould Stable PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,999,690 B2

DATED

February 14, 2006

INVENTOR(S) :

Yasunari WATANABE, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9:

Line 37, "start" should read --starts--; and Line 41, "let a" should read --let α --.

COLUMN 11:

Line 34, "developing the" should read --developing--; and Line 57, "+300" should read --+300V--.

COLUMN 14:

Line 15, "sold-state" should read --solid-state--.

COLUMN 16:


Line 4, "OV." should read --0V.--; and Line 25, "OV." should read --0V.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. 6,999,690 B2

No. of add'l. copies @ 30¢ per page







IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	Examiner: Hoang Ngo
Yasunari WATANABE, et al.	;)	
U.S. Patent No.: 6,999,690 B2	;	Group Art Unit: 2852
Issued: February 14, 2006	<u>;</u>	Confirmation No.: 2715
Appl. No.: 10/617,024	:	
••	:	
Filed: July 11, 2003	;	L 12, 2006
For: IMAGE FORMING APPARATUS)	June 12, 2006

Commissioner for Patents Post Office Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our New York office at the address given below.

Respectfully submitted,

William M. Wannisky
Attorney for Patentees
Registration No. 28,373

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 Facsimile: (212) 218-2200

WMW\tas

DC_MAIN 242785v1

Stable Here Oulding TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,999,690 B2

DATED

February 14, 2006

INVENTOR(S) :

Yasunari WATANABE, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4:

Line 42, "cylinder" should read --cylinder (conductive drum substrate) 1a.--; Line 44, "(Conductive Drum Substrate) 1a." should be deleted.

COLUMN 5:

Line 1, "an" should read --a--;

Line 2, "roller," should read --roller, and the surface layer 2d is a protection layer provided for preventing a leak from occurring even if a flaw such as a pinhole exists on the photosensitive drum 1. To be more specific, specifications of the charging roller--;

Line 10, "The" should read -- The--; and

Line 15, "Surface" should read -- Surface--.

COLUMN 7:

Line 15, "rum 1" should read --drum 1--;

Line 26, "copy)" should read --copy) .--; and

Line 53, "work." should read --work. Further, this cleanerless system has a merit in terms of downsizing the image forming apparatus. According to this embodiment, the transfer residual toner on the surface of the photosensitive drum 1 after being the transferred, is conveyed to the developing portion "c" via the charging portion "a" and the exposing portion "b" as the photosensitive drum 1 subsequently rotates, and is cleaned (collected) simultaneously with developing by the developing device 4.--.

COLUMN 8:

Line 26, "charging" should read --improper charging--; and Line 27, "improper" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. 6,999,690 B2

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82) WMW\tas

Stable Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,999,690 B2

DATED

February 14, 2006

INVENTOR(S) :

Yasunari WATANABE, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9:

Line 37, "start" should read --starts--; and Line 41, "let a" should read --let α --.

COLUMN 11:

Line 34, "developing the" should read --developing--; and Line 57, "+300" should read --+300V--.

COLUMN 14:

Line 15, "sold-state" should read --solid-state--.

COLUMN 16:

Line 4, "OV." should read --0V.--; and Line 25, "OV." should read --0V.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. 6,999,690 B2

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82)

WMW\tas